



October 9, 2020

Re: Water Sample Results

On Thursday, October 8, 2020, the City of Rosenberg received results from water samples collected from the Brazosport Water Authority surface water supply entry point at Water Plant 8 and various locations throughout the city's water distribution system. The results did not detect any of the *Naegleria Fowleri* amoeba from any of the samples. With this additional level of assurance, the City of Rosenberg will begin reintroducing treated surface water back into the water distribution system today.

Should you require additional information, please contact me at (832) 595-3591.

Sincerely,

A handwritten signature in black ink, appearing to be "Rigo Calzoncin".

Rigo Calzoncin
Executive Director of Public Services

RC

attach: Test results

xc: John Maresh, City Manager
Heriberto DeLeon, Utility Director



Sample collection		Sample received		Completed		Requisition
Date	Time	Date	Time	Date	Time	
09-28-2020	1211	09-28-2020	1542	10-07-2020	1948	M41767

Customer	Envirodyne Laboratories
Street	11011 Brooklet Drive, Suite 230
City, State, Zip	Houston, TX 77099
Phone	(281)568-7880

Laboratory Results

Sample Collection Site: Water Plant #8 (BWA Incoming Water)

Sample Matrix: Aqueous

Total Volume Analyzed: 5 Gallons

Analyte	Test Method	Result	Units	Qualifiers
<i>Naegleria fowleri</i>	SM 9711	None Seen	amoeboid/gal	None

Narrative:

Complete reporting of deviations from method requirements, regardless of the suspected impact on the data is required. Quality control failures not reported within a report summary are noted here.

The following quality control failures were noted: None
 The following qualifiers were identified: None

Reference:
 Standard Methods 23rd Edition. 2017.
 Manual of Environmental Microbiology, Second Edition. 2002.

QA Review: RF

Approved by: Paul J. Pearce (SM/ASCP) Date: 10/08/2020
 Paul J. Pearce, Ph.D.
 Laboratory Director
 Specialist of Microbiology (SM/ASCP Board of Certification)

The results shown on this report refer only to the sample(s) tested unless otherwise stated. No further evaluation of these results is made by Nova Biologicals, Inc. This report cannot be reproduced except in full, without prior written consent of Nova Biologicals, Inc.



Sample collection		Sample received		Completed		Requisition
Date	Time	Date	Time	Date	Time	
09-28-2020	1214	09-28-2020	1539	10-07-2020	1942	M41768

Customer	Envirodyne Laboratories
Street	11011 Brooklet Drive, Suite 230
City, State, Zip	Houston, TX 77099
Phone	(281)568-7880

Laboratory Results

Sample Collection Site: Water Plant #8 (GST)

Sample Matrix: Aqueous

Total Volume Analyzed: 5 Gallons

Analyte	Test Method	Result	Units	Qualifiers
<i>Naegleria fowleri</i>	SM 9711	None Seen	amoeboid/gal	None

Narrative:

Complete reporting of deviations from method requirements, regardless of the suspected impact on the data is required. Quality control failures not reported within a report summary are noted here.

The following quality control failures were noted: None

The following qualifiers were identified: None

Reference:

Standard Methods 23rd Edition. 2017.

Manual of Environmental Microbiology, Second Edition. 2002.

QA Review: RF

Approved by: Paul J. Pearce (AMP) Date: 10/08/2020
 Paul J. Pearce, Ph.D.
 Laboratory Director
 Specialist of Microbiology (SM/ASCP Board of Certification)

The results shown on this report refer only to the sample(s) tested unless otherwise stated. No further evaluation of these results is made by Nova Biologicals, Inc. This report cannot be reproduced except in full, without prior written consent of Nova Biologicals, Inc.



Sample collection		Sample received		Completed		Requisition
Date	Time	Date	Time	Date	Time	
09-28-2020	1327	09-28-2020	1541	10-07-2020	1936	M41769

Customer	Envirodyne Laboratories
Street	11011 Brooklet Drive, Suite 230
City, State, Zip	Houston, TX 77099
Phone	(281)568-7880

Laboratory Results

Sample Collection Site: 4901 Cotter Ln.
Sample Matrix: Aqueous
Total Volume Analyzed: 5 Gallons

Analyte	Test Method	Result	Units	Qualifiers
<i>Naegleria fowleri</i>	SM 9711	None Seen	amoeboid/gal	None

Narrative:

Complete reporting of deviations from method requirements, regardless of the suspected impact on the data is required. Quality control failures not reported within a report summary are noted here.

The following quality control failures were noted: None
The following qualifiers were identified: None

Reference:
Standard Methods 23rd Edition. 2017.
Manual of Environmental Microbiology, Second Edition. 2002.

QA Review: RF

Approved by: Paul J. Pearce (amp) Date: 10/08/2020
Paul J. Pearce, Ph.D.
Laboratory Director
Specialist of Microbiology (SM/ASCP Board of Certification)

The results shown on this report refer only to the sample(s) tested unless otherwise stated. No further evaluation of these results is made by Nova Biologicals, Inc. This report cannot be reproduced except in full, without prior written consent of Nova Biologicals, Inc.



Sample collection		Sample received		Completed		Requisition
Date	Time	Date	Time	Date	Time	
09-28-2020	1238	09-28-2020	1541	10-07-2020	1930	M41770

Customer	Envirodyne Laboratories
Street	11011 Brooklet Drive, Suite 230
City, State, Zip	Houston, TX 77099
Phone	(281)568-7880

Laboratory Results

Sample Collection Site: EST #5 (Minonite)

Sample Matrix: Aqueous

Total Volume Analyzed: 5 Gallons

Analyte	Test Method	Result	Units	Qualifiers
<i>Naegleria fowleri</i>	SM 9711	None Seen	amoeboid/gal	None

Narrative:

Complete reporting of deviations from method requirements, regardless of the suspected impact on the data is required. Quality control failures not reported within a report summary are noted here.

The following quality control failures were noted: None

The following qualifiers were identified: None

Reference:

Standard Methods 23rd Edition. 2017.

Manual of Environmental Microbiology, Second Edition. 2002.

QA Review: RF

Approved by:

Paul J. Pearce (Auth) Date: 10/08/2020

Paul J. Pearce, Ph.D.

Laboratory Director

Specialist of Microbiology (SM/ASCP Board of Certification)

The results shown on this report refer only to the sample(s) tested unless otherwise stated. No further evaluation of these results is made by Nova Biologicals, Inc. This report cannot be reproduced except in full, without prior written consent of Nova Biologicals, Inc.



Sample collection		Sample received		Completed		Requisition
Date	Time	Date	Time	Date	Time	
09-28-2020	1334	09-28-2020	1540	10-07-2020	2010	M41771

Customer	Envirodyne Laboratories
Street	11011 Brooklet Drive, Suite 230
City, State, Zip	Houston, TX 77099
Phone	(281)568-7880

Laboratory Results

Sample Collection Site: 1105 Wilson Dr.
Sample Matrix: Aqueous
Total Volume Analyzed: 5 Gallons

Analyte	Test Method	Result	Units	Qualifiers
<i>Naegleria fowleri</i>	SM 9711	None Seen	amoeboid/gal	None

Narrative:

Complete reporting of deviations from method requirements, regardless of the suspected impact on the data is required. Quality control failures not reported within a report summary are noted here.

The following quality control failures were noted: None
The following qualifiers were identified: None

Reference:
Standard Methods 23rd Edition. 2017.
Manual of Environmental Microbiology, Second Edition. 2002.

QA Review: RF

Approved by: Paul J. Pearce (SM/ASCP) Date: 10/08/2020
Paul J. Pearce, Ph.D.
Laboratory Director
Specialist of Microbiology (SM/ASCP Board of Certification)

The results shown on this report refer only to the sample(s) tested unless otherwise stated. No further evaluation of these results is made by Nova Biologicals, Inc. This report cannot be reproduced except in full, without prior written consent of Nova Biologicals, Inc.



Sample collection		Sample received		Completed		Requisition
Date	Time	Date	Time	Date	Time	
09-28-2020	1252	09-28-2020	1540	10-07-2020	2000	M41772

Customer	Envirodyne Laboratories
Street	11011 Brooklet Drive, Suite 230
City, State, Zip	Houston, TX 77099
Phone	(281)568-7880

Laboratory Results

Sample Collection Site: 7811 Lake Commons Dr.

Sample Matrix: Aqueous

Total Volume Analyzed: 5 Gallons

Analyte	Test Method	Result	Units	Qualifiers
<i>Naegleria fowleri</i>	SM 9711	None Seen	amoeboid/gal	None

Narrative:

Complete reporting of deviations from method requirements, regardless of the suspected impact on the data is required. Quality control failures not reported within a report summary are noted here.

The following quality control failures were noted: None
 The following qualifiers were identified: None

Reference:
 Standard Methods 23rd Edition. 2017.
 Manual of Environmental Microbiology, Second Edition. 2002.

QA Review: PF

Approved by: Paul J. Pearce ^(AMP) Date: 10/08/2020
 Paul J. Pearce, Ph.D.
 Laboratory Director
 Specialist of Microbiology (SM/ASCP Board of Certification)

The results shown on this report refer only to the sample(s) tested unless otherwise stated. No further evaluation of these results is made by Nova Biologicals, Inc. This report cannot be reproduced except in full, without prior written consent of Nova Biologicals, Inc.



Sample collection		Sample received		Completed		Requisition
Date	Time	Date	Time	Date	Time	
09-28-2020	1351	09-28-2020	1542	10-07-2020	1956	M41773

Customer	Envirodyne Laboratories
Street	11011 Brooklet Drive, Suite 230
City, State, Zip	Houston, TX 77099
Phone	(281)568-7880

Laboratory Results

Sample Collection Site: 1213 Louise St.

Sample Matrix: Aqueous

Total Volume Analyzed: 5 Gallons

Analyte	Test Method	Result	Units	Qualifiers
<i>Naegleria fowleri</i>	SM 9711	None Seen	amoeboid/gal	None

Narrative:

Complete reporting of deviations from method requirements, regardless of the suspected impact on the data is required. Quality control failures not reported within a report summary are noted here.

The following quality control failures were noted: None

The following qualifiers were identified: None

Reference:

Standard Methods 23rd Edition. 2017.

Manual of Environmental Microbiology, Second Edition. 2002.

QA Review: RF

Approved by:

Paul J. Pearce (AMP)
Date: 10/08/2020

Paul J. Pearce, Ph.D.

Laboratory Director

Specialist of Microbiology (SM/ASCP Board of Certification)

The results shown on this report refer only to the sample(s) tested unless otherwise stated. No further evaluation of these results is made by Nova Biologicals, Inc. This report cannot be reproduced except in full, without prior written consent of Nova Biologicals, Inc.



Sample collection		Sample received		Completed		Requisition
Date	Time	Date	Time	Date	Time	
09-28-2020	1407	09-28-2020	1542	10-07-2020	1956	M41774

Customer	Envirodyne Laboratories
Street	11011 Brooklet Drive, Suite 230
City, State, Zip	Houston, TX 77099
Phone	(281)568-7880

Laboratory Results

Sample Collection Site: 5606 Cunningham Ln.
Sample Matrix: Aqueous
Total Volume Analyzed: 5 Gallons

Analyte	Test Method	Result	Units	Qualifiers
<i>Naegleria fowleri</i>	SM 9711	None Seen	amoeboid/gal	None

Narrative:

Complete reporting of deviations from method requirements, regardless of the suspected impact on the data is required. Quality control failures not reported within a report summary are noted here.

The following quality control failures were noted: None
The following qualifiers were identified: None

Reference:
Standard Methods 23rd Edition. 2017.
Manual of Environmental Microbiology, Second Edition. 2002.

QA Review: RF

Approved by: Paul J. Pearce (AMP) Date: 10/08/2020
Paul J. Pearce, Ph.D.
Laboratory Director
Specialist of Microbiology (SM/ASCP Board of Certification)

The results shown on this report refer only to the sample(s) tested unless otherwise stated. No further evaluation of these results is made by Nova Biologicals, Inc. This report cannot be reproduced except in full, without prior written consent of Nova Biologicals, Inc.